

CORNER HISTORY:

CORNER FILE CODE: T6S-R9W-J-11

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec., 1805 (missing notes).

COUNTY SURVEYOR'S BOOKS: Book 1 P. 30: Isaac Adams WCS Sept. 1, 1854 "Wood Post"

OTHER SURVEYS AND PLATS: No Co. Surv. references, no recorded surveys/subdivisions found.

A 5/8" rebar was found and tied in to the Telephone Road Route Survey (Bernardin-Lochmueller & Assoc.) 2002. This rebar was shown on a previous survey of Telephone Road by Warrick Engineering (1990-1991) as "Found 5/8" I.P. at aerial panel".

VERIFICATION OF CORNER POSITION: September, 2002: The rebar shown was found in place and referenced. Checks were made to verify its position relative to Telephone Road alignment points (as shown). The history of this rebar prior to the Warrick Engineering survey of Telephone Road is unknown. No deeds were found which would help verify its position. The rebar is located approximately 3' west and 17' north of the midpoint between the southwest and southeast corners of Section 9. It is approximately in line with a field divide running to the south. The rebar was accepted as the apparent corner only on the basis that it is on existing monument, reasonably consistent with possession lines and record chainage, and no contradictory evidence was found.

June, 2005: The rebar was found along with the reference points. Some reference points were measured accurate using a tape, points longer than 200' were not measured.

COMMENTS/RECOMMENDATIONS: Planned future improvements to Telephone Road may provide the opportunity to search beneath pavement level for an old stone or other evidence to further verify this position.

Perry E. Jones 9/25/02

Brian Schnur and Dan Grady 6/17/05