

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec. 21(?), 1805 "Post" (@39.92ch/79.84ch) COUNTY

SURVEYOR'S BOOKS: Book 1 P. 175: John C. Frary WCS Nov. 4, 1859 Stone Marked" Book 1 P. 252: O.B.Pasco WCS Nov. 26, 1866 (Mon. not identified)"

OTHER SURVEYS AND PLATS: "Corner Record" cards show a 1983 [ref. to](#) a 5/8" IP, and a 1990 [ref. to](#) 0 5/8" IP taken from the plot of LaBelle Manor.

A plot of survey by Rodney K. Young dated July 30, 1992 (Surv. File 1, Card 360) shows a 3/4" IP 1" below grade.

VERIFICATION OF CORNER POSITION: September, 2002: A 5/8" rebar was found in place, slightly bent. Its position was generally consistent with previous reference ties (+/- 1). It appears likely that the 1990 reference tie distance of 33.08' from a curb corner should have been 34.08', which would match very closely the other two 1990 reference ties. If so, this would indicate a position approximately 0.1' south and 0.2' east of the rebar as found. Considering the possible movement of utility poles over a period of years, however, the rebar was referenced in position as found. October 28, 2003: the bent rebar was removed and replaced with the disk shown.

Perry E. Jones 10/29/03