

## CORNER HISTORY:

CORNER FILE CODE: T6S-R9W-J-09

ORIGINAL USPLS SURVEY: Corner

established by Jacob Fowler, Dec., 1805

(missing notes). COUNTY SURVEYOR'S

BOOKS: Book 1 P. 30: Isaac Adams WCS Sept.

1, 1854 "Wood Post" Book 1 P. 129: John C.

Frory WCS Dec. 17, 1859 "Established by

Adams". OTHER SURVEYS AND PLATS:

"Corner Code System" card shows ref, to I.P.

1/2" Pipe Found shown on plot of survey by

Donny K. Leek (Doc. 1998R-001641).

A boot spike, 2" below grade, was tied in to the Telephone Road Route Survey (Bernardin-Lochmueller & Assoc.) 2002. The telephone and power poles shown on the old Corner Code System card reference were gone, but the boot spike's position relative to monuments found (approximately) 1/4 mile and 1/2 mile west matched the Danny Leek survey within 0.05 feet.

VERIFICATION OF CORNER POSITION: September, 2002: The boot spike shown was found in place and referenced. Checks were made to other alignment points from the Telephone Road survey (as shown).

COMMENTS/RECOMMENDATIONS: Planned future improvements to Telephone Road may provide the opportunity to search beneath pavement level for an old stone or other evidence to further verify this position. Perry E. Jones  
9/25/02