

CORNER HISTORY:

CORNER FILE CODE:
T6S-R9W-N-09

ORIGINAL USPLS SURVEY: Corner established by Jacob Fowler, Dec 20, 1805 "Post". COUNTY

SURVEYOR'S BOOKS: Book 1 P. 30: Isaac Adams WCS Sept. 1, 1854 "Wood Post" Book 2 P. 164: Louis

Meyer WCS May 20, 1901 "SandStone Set" Book 3 P. 161: Louis Meyer WCS March 21, 1911 "Old Corner"

Book 3 P. 237: Samuel Bohannon WCS April 24, 1919 "Old corner"

OTHER SURVEYS AND PLATS: A plat of survey by John W. Curry dated 12/30/87 shows a RR spike set at the corner (does not describe how the position was established).

A plot of survey by Donald Ray Adler (Doc. 1995R-211) showed no monument at the corner, with a calculated position based on ties to the 1987 Curry survey. Mr. Adler noted that the position did not match dimensions from the County Surveyor's corner records.

VERIFICATION OF CORNER POSITION: March, 2003; no monument was found; the 1987 Curry survey was used to re-establish the corner, using his ^{angle} and distance from the north quarter corner of section 20 as shown. The resulting position aligned well with the existing centerline of Oak Grove Road and with a dredged ditch running south from the corner (these physical features may in fact have been used by Mr. Curry to re-establish the corner). A railroad spike was set and referenced. October 27, 2003: the spike was replaced with the aluminum disk shown.

Perry E. Jones 10/28/03